1 BACKGROUND

Fugro EarthData (Fugro) was tasked as the Quality Control (QC) manager for the North Carolina statewide orthophotography project under AECOM's North Carolina contract. The main responsibilities covering this task were to do a quality assurance check of the aero triangulation (AT) report, ensure orthophotography tiles were standardized in their delivery, perform a percentage check of tiles for errors, and generate MrSID tiles and mosaics for all accepted data.

2 PROCEDURE

To achieve the quality objectives Fugro designed the following process that was implemented during the AT QC execution. Fugro was not tasked to seal the AT results but to do a quality assurance check of the results.

2.1 Block Integrity Check:

In this step, the actual block layout compared to the executed AT block to ensure that the contractor adhered to the original design of AT blocks and ground control layout. Discrepancies were sent back to the contractor for correction.

2.2 Ground Controls Integrity Check:

This step was performed at the same time as 2.1. The ground control numbers and configuration are examined and any discrepancies were reported for correction or clarification (see figure 1).




Figure 1 Photo centers, tie/pass, and control layout

2.3 Tie/pass points Integrity Check:

In this step a visual examination of the density and distribution of the tie/pass points was performed (see figure 1) and discrepancies were reported for correction or clarification.

2.4 Bundle Block Adjustment Setup Examination:

In this step, the final report from the bundle block adjustment was examined in order to make sure that the statistics meet the final project accuracy specifications. Final accuracy specifications were developed for the project after the first few blocks were submitted for review and it became clear that vendors needed more guidance on the measure of acceptability (Figure 2). Details of bundle adjustment setup (see figure 3) and weight on the ABGPS and ground control points (see figure 4) are reviewed and discrepancies were reported for correction or clarification.

| | Tested Characteristic | Measure of Acceptability |
|-----|---|--|
| 40. | Horizontal accuracy against ground control check | RMSE = 0.8 ft for imagery with 6" GSD |
| | points tested in accordance with 10+ points at NSSDA | (to support ortho generation according to |
| | criteria | ASPRS mapping standard class II) |
| 41. | Vertical accuracy against ground control check points | 0.8 ft for imagery with 6" GSD |
| | tested in accordance with 10+ points at NSSDA | (to support ortho generation according to |
| | criteria | ASPRS mapping standard class II) |
| 42. | Accuracy against image coordinates | RMSE less than or equal to 5 microns is |
| | | acceptable. |
| 43. | Max. offsets [E, N] to any one blind QA point | 3 * RMSE or 2.4 ft |
| 44. | RMSE at airborne GPS residuals in E,N,H | Acceptable RMSE at GPS residuals generally |
| | | less than 15 cm. |

Figure 2 AT accuracy specifications

GCP observations: Enabled GPS observations: Enabled IMU observations: Enabled Error Detection: Disabled Self-Calibration: Disabled Precision Computation: Enabled

Figure 3 Block adjustment setup

| ID | Х | Υ | Z | VX | VY | VXY | VZ | Std Dev X | Std Dev Y | Std Dev Z rx ry rz | RMSVX | RMSV | Y RMSVZ |
|--------|----------------|-------------|-----------|---------|---------|--------|---------|-----------|-----------|-----------------------|--------|--------|---------|
| | | | | | | | | | | | | | |
| 65212 | 4 1483337.5500 | 846357.2400 | 5601.2400 | 0.1430 | -0.0259 | 0.1453 | 0.2341 | 0.1599 | 0.1702 | 0.0968 0.22 0.12 0.71 | 0.0854 | 0.0624 | 0.1533 |
| 65212 | 3 1483339.3600 | 844907.4900 | 5605.0500 | 0.1368 | -0.1818 | 0.2275 | 0.3451 | 0.1469 | 0.1600 | 0.0817 0.34 0.22 0.80 | 0.1062 | 0.0852 | 0.1618 |
| 65212 | 2 1483350.4600 | 843441.6800 | 5604.3900 | 0.2439 | -0.2686 | 0.3628 | 0.2178 | 0.1444 | 0.1591 | 0.0776 0.37 0.23 0.82 | 0.1096 | 0.0869 | 0.1638 |
| 65212 | 1 1483360.0600 | 841964.7000 | 5599.6500 | -0.0421 | -0.2888 | 0.2918 | 0.1812 | 0.1461 | 0.1619 | 0.0784 0.35 0.20 0.81 | 0.1073 | 0.0815 | 0.1634 |
| 65212 | 1483368.6600 | 840491.9700 | 5594.8600 | 0.1492 | -0.2969 | 0.3323 | -0.0627 | 0.1491 | 0.1625 | 0.0807 0.32 0.20 0.80 | 0.1031 | 0.0803 | 0.1623 |
| 652119 | 9 1483366.6800 | 839017.6800 | 5597.7800 | -0.0071 | -0.1864 | 0.1865 | 0.0455 | 0.1466 | 0.1586 | 0.0801 0.35 0.23 0.80 | 0.1066 | 0.0878 | 0.1626 |
| 652118 | 3 1483360.1800 | 837528.8300 | 5599.3000 | 0.1478 | -0.2209 | 0.2658 | 0.0133 | 0.1481 | 0.1602 | 0.0807 0.33 0.22 0.80 | 0.1046 | 0.0849 | 0.1623 |

Figure 4 Weight and accuracy of adjusted parameters of the ABGPS

2.5 Bundle Block Adjustment Results Examination:

In this step, the final results of the ground controls fit were examined in order to ensure that it was meeting the contractual specifications (see figure 5)

```
Y/Phi Z/Kappa
                      Parameter X/Omega
                                                           XY
                RMS Control
                             0.268
                                          0.242 0.240
                                                          0.361
                            1.000 1.000 1.000
                RMS Limits
        Max Ground Residual 0.499 0.649
                                             0.625
       Residual Limits 3.000 3.000 3.000 Mean Std Dev Object 0.08471 0.07992
                                               3.000
                                                  0.19470
        RMS Photo Position 0.095
                                       0.177
                                                  0.115
         RMS Photo Attitude
                            0.006599 0.004279
                                                  0.021666
Mean Std Dev Photo Position
                             0.1527
                                       0.1637
                                                  0.0865
```

```
0.001930 0.001662
                                                  0.000975
Mean Std Dev Photo Attitude
Current Count
       Control Points Used:
       Photos Used: 5104
        Photos Not Used:
                             17089
       Image Points Used:
```

Figure 5 Final accuracy of adjusted block

ISSUES ENCOUNTERED

The following issues were observed in various AT reports and communicated back to the vendor and the program manager.

3.1 Blocks design deviated from the original block design:

Some contractors altered the boundary of the blocks due to various legitimate and illegitimate reasons. Among the legitimate reasons were terrain difficulty which made it impossible to collect ground controls as it was laid out in the original design, therefore the blocks were re-aligned to better fit the surveyed ground controls.

3.2 Not enough tie/pass points between adjacent blocks:

Some blocks did not have enough tie points in order to assure accurate transition from one block to another.

3.3 Assigned priority weights were either too loose or too tight:

Some contractors applied unsuitable constraints on the adjusted observations in the AT bundle block adjustment.

RESOLUTIONS

Based on the issues encountered three resolutions could be applied to avoid such encounters on future programs.

- AT accuracy specifications should be specified clearly at the RFP or contracting stage so that vendors clearly understand the production expectations. This would also ensure proper AT block design and ground control point (GCP) design.
- Adding blind points at the AT stage would allow vendors and QC firm/s to confirm the quality of the AT solution.
- Ensure that the difficulty of terrain be taken into account during the design of the AT blocks and the GCP layout development.

Date written: 01.24.2011

Contributors:

Dr. Qassim Abdullah John C. Knowlton III